

# Official Survey Record

THAYER — — — — — COUNTY, NEBRASKA

Page 12 of 12

## Field Notes:

### NE Corner Section 14-T1N-R1W

Found 3/4" Iron Pipe 3" deep recorded as over Magnet. After Construction found 3/4" Iron Pipe 3" deep. Temporary ties are as follows.

SSE 106.60' to top NW corner of concrete right of way marker  
SSW 126.71' to nail and shiner East side power pole  
NW 45.72' to top center point of telephone underground box  
N 31.34' to 5/8" X 24" rebar with tag "RM WW02" in North  
right of way fence 0.5' East of witness post  
NE 40.94' to 5/8" X 24" rebar with tag "RM WW02" in North  
right of way fence 25' East of witness post  
N 31 ' to Witness Post  
S 47 ' to centerline Highway 8

### NE Corner Section 13-T1N-R1W

Found Aluminum Cap at surface recorded on a 5/8" X 3" Rebar. Cap and Bar are over a 1/2" X 10" Pipe with NDOR Brass Cap 6" deep. Found 5/8" X 22" Rebar 15" deep. Found Sandstone 0.70' North-South by 0.50' East-West 31" deep. Brass Cap and Aluminum Cap are 0.07' East of Stone. Rebar is 0.07' East and 0.13' North of Stone. Set Aluminum Cap to 25". Set Brass Cap in Pipe to 15". Set 5/8" Rebar to 9". Set Magnet on Stone. After construction, set 5/8" X 24" Rebar to grade at surface of Asphalt with Aluminum Cap marked

THAYER COUNTY 2002

GC

R1W R1E

S12 S 7

S13 S18

T1N

SECTION CORNER

with temporary ties to Stone as follows.

ENE 119.83' to top SW corner "Marks Mill" historical marker  
SSW 84.23' to nail and shiner East side power pole  
NNE 53.83' to nail and shiner West side telephone underground  
post  
NNW 60.56' to nail and shiner East side power pole  
SSE 83.72' to top NW corner concrete right of way marker  
S 18 ' to centerline Highway 8  
On centerline North-South road